

# THE PERFORMANCE GAP PROJECT

---

Closing the Gap Between  
Design & As Built



15<sup>th</sup>. September 2014



# ROLE OF THE ZERO CARBON HUB

## PURPOSE AND STRATEGIC OBJECTIVES

*Facilitate the mainstream delivery of low and zero carbon homes working across borders*

- Provide leadership and create confidence
- Reduce risk
- Disseminate information



---

# The Performance Gap



**Mending the Gap**

# FABRIC FIRST - Energy efficiency

Building Fabric:


U-values

Thermal mass  
Thermal Bridging


Air-permeability

Orientation, solar gains,

Glazing proportion



# Industry WG Structure



---

# Interim Report

## The Problems!



---

## CROSS-CUTTING THEMES



KNOWLEDGE & SKILLS



RESPONSIBILITY



COMMUNICATION

# Literature Review



- **State of the industry (*aggregated data*)**
  - NHBC, LABC, SAP software providers, professional institutions, house builders, manufacturers
- **Compliance processes**
  - As-built SAPs, ACD/ECD use, Air pressure tests, commissioning
- **Field trials**
  - TSB Building Performance Evaluation, EST Heat pump trials
- **Academic studies**
  - Stamford Brook, Elmtree Mews, Temple Avenue
- **“Secret” knowledge**
  - Manufacturers, Universities

---

# Housebuilding Process Review


- 21 sites analysed
- Over 200 units
- Completely anonymous
- Identified many issues




---

# Evidence Review

The truth behind  
the myths.



## Prioritisation of issues



## - 15 Priority for Action

AND cross-cutting themes



KNOWLEDGE & SKILLS



RESPONSIBILITY



COMMUNICATION

## Evidence Review Report



## CONCEPT DESIGN & PLANNING



Limited understanding of impact of early design decisions on energy performance

## DETAILED DESIGN



Inadequate understanding and knowledge within detailed design team

D2

Lack of integrated design between fabric, services & renewables



Issues around use of U-value and thermal bridging calculation procedures

EM7

Concern over competency of SAP assessors

## PROCUREMENT



Inadequate consideration of skills and competency at labour procurement

## CONSTRUCTION & COMMISSIONING



Product substitution on site without consideration of energy performance



Poor installation of fabric



Poor installation or commissioning of services



Lack of site team energy performance knowledge & skills



Lack of adequate energy performance related QA on site

## VERIFICATION & TESTING



Concern over consistency of some test methodologies & interpretation of data



As-Built SAP not reflective of actual build



Lack of robust energy performance related verification, reliance on third party information



Lack of clarity over documentary evidence for Part L & Part F compliance


---

# 1. Inadequate Understanding & Knowledge within Design Team

- Impact on:
  - Buildability
  - Compatability of systems, materials and services
  - Thermal detailing
- Typical examples:
  - Details into which insulation is impossible to fit
  - No detail on support of screed at ground floor perimeters
  - No consideration of thermal bridges for rooms over garages
  - Etc....


○ Design Assumed:

- Wall ties
- Compressed edge seal
- Insulation



○ Reality:

- Wall ties ✓
- Compressed edge seal ✗
- Insulation ✗



---

## 2. Concern over Competency of SAP Assessors

- Problems with:
  - Accuracy of inputs
  - Following conventions
  - Validating assumptions
  - Evidencing assessments

---

## 2. Concern over Competency of SAP Assessors

- Problems with:
  - Accuracy of inputs
  - Following conventions
  - Validating assumptions
  - Evidencing assessments




Massive impact where they are giving design advice

## ○ How is the u-value calculated?



Can't assume same thickness across entire roof



---

# 3. Lack of Site Team Energy Performance Related Knowledge and Skills and/or Care

## ○ Literature Review -

- *“The lack of proper training of the workforce.....resulted in significant construction faults, unplanned design solutions and wrong system commissioning”*

**Oxford Brookes University, *Understanding the Gap between As Designed and As Built Performance, 2013***



---


# 3. Lack of Site Team Energy Performance Related Knowledge and Skills and/or Care

- Literature Review -

- *“The lack of proper training of the workforce.....resulted in significant construction faults, unplanned design solutions and wrong system commissioning”*

**Oxford Brookes University, *Understanding the Gap between As Designed and As Built Performance*, 2013**

- Windows located in front of design positions
  - Insufficient overlap with cavity closer
  - 8 out of 9 sites visited



---

## 4. Product Substitution On Site

### ○ Literature Review -

- *“The most striking observation about the application of materials and components were the number of occasions on which materials intended for one location were used in another”*

**Leeds Metropolitan University, Lessons from Stamford Brook, 2008**

### ○ Housebuilding Process Review -

- Identified on all sites reviewed
- Blockwork & windows

# INDUSTRY RECOMMENDATIONS

---



---

## 1 - PERFORMANCE ASSESSMENT R&D

*Undertake the research and development necessary to create innovative testing, measurement and assessment techniques to understand the performance gap and develop commercially viable methodologies acceptable across industry for 'demonstrating performance'*

## 2 - SKILLS AND KNOWLEDGE DEVELOPMENT

*Ensure that as-built energy performance knowledge, including learning from on going research and development, is embedded into training and up-skilling for professionals and trades.*

---

### 3 - CONSTRUCTION DETAILS SCHEME

*Develop an industry owned and maintained construction details scheme providing 'assured' as-built energy performance for the most common major fabric junctions and systems.*

### 4 - CONTINUED EVIDENCE GATHERING

*Support further evidence gathering processes and coordinated feedback to ensure accelerated continual improvement across all sectors of industry .*

# GOVERNMENT RECOMMENDATIONS

---



---

# 1 - SIGNAL CLEAR DIRECTION

*Clearly indicate that, in place of immediate additional regulation, it expects the construction industry to act now and have put in place a number of measures to ensure that the energy performance gap is being addressed and to demonstrate this by 2020.*

---

## 2 - STIMULATE INDUSTRY INVESTMENT

*By funding research and development into testing, measurement and assessment techniques with immediate effect, to support the industry in providing the information necessary to quantify the performance gap and create the learning loops required to drive continuous improvement.*

*Additionally provide pump prime funding to enable industry to develop a construction details scheme.*

---

## 3 - STRENGTHEN COMPLIANCE REGIME

*Take action by 2016 to ensure that the Zero Carbon Hub recommended revisions to energy modelling practices, SAP processes and verification procedures, together with a strong regime to ensure that only suitably qualified persons carry out energy modelling, can be put in place.*

---

## 4 - SUPPORT SKILLS & KNOWLEDGE DEVELOPMENT

*Accelerate the demand for industry developed qualification schemes by requiring energy certified trades and professionals for all developments on public land from 2017.*

# ROUTE MAP TO 2020

---


The challenge ahead




KEY

- Energy literacy
- Improving quality output
- National compliance regime
- Demonstrating performance
- Continued evidence gathering

INDUSTRY LED INNOVATIONS



GOVERNMENT SUPPORT



**Thankyou !**



Err .... Can I have my bike back please